


Resets for Controllers

SP54500 & SP500A MKI & SP1000 Controllers - Turn the Power Off to the Spa. Wait a minimum of 20 minutes to allow the heater tube to cool. Press all thermal overload resets. Turn the Power back On again.

SP500A MKII & SP750 - Turn the Power Off to the Spa. Wait a minimum of 20 minutes to allow the heater tube to cool. Turn the Power back On again.

To Reset the SP400/600/601 and Xcelsior Spa Pool System wait a minimum of 20 minutes to allow the heater tube/area to cool. Then press the down, up and pump buttons all simultaneously and hold for 3 seconds.



To Reset the SP800 & SP1200 wait a minimum of 20 minutes to allow the heater tube to cool. Then press the two light buttons and the blower (SP800)/pump2 on/off (SP1200) and pump1 on/off button all simultaneously and hold for 3 seconds.

